

FIG.1




FIG.4

2/3

C_1	00000001	C_1^{bc}
C_1	00000010	C_1^{RACH}
C_1	00000011	C_1^1
C_1	00000100	C_1^2
C_2	00010000	C_2^{bc}
C_2	00000001	C_2^{RACH}
C_2	00000010	C_2^1
C_2	00000100	C_2^2
C_5	00100000	C_5^{bc}
C_5	00100001	C_5^{RACH}
C_5	00100010	C_5^1
C_5	00100011	C_5^2

FIG.2

